



## PRODUCT DETAILS

### CALIPER PIN REPAIR KIT



**ARSKAR NEIN**

160 840 397

**MARKE**

MERITOR

**REFERENZNUMMER**

MCK1116, 85102094, AMMCK1116,  
1489197, STRMCK1116, 5021202776

**PAKET EINHEIT**

1 stck

### PRODUKTE ENTHALTEN



**CALIPER PIN - Ø 35 / 102 MM / 1 EINHEIT**

**ARSKAR NEIN:** 160 840 077

**REFERENZNUMMER:** -



**CALIPER PIN - Ø 35 / 60 MM / 1 EINHEIT**

**ARSKAR NEIN:** 160 840 080

**REFERENZNUMMER:** -



**CALIPER PIN BOLT - M20 X 2 / 125 MM / 1 EINHEIT**

**ARSKAR NEIN:** 160 840 078

**REFERENZNUMMER:** -



**CALIPER PIN BOLT - M20 X 2 / 80 MM / 1 EINHEIT**

**ARSKAR NEIN:** 160 840 081

**REFERENZNUMMER:** -



**CALIPER PIN FIBER BUSH - Ø 35 X 39 / 77 MM / 1 EINHEIT**

**ARSKAR NEIN:** 160 840 253

**REFERENZNUMMER:** -



**CALIPER PIN OVAL BUSH - Ø 35-36 X 39 / 30 MM / 1 EINHEIT**

**ARSKAR NEIN:** 160 840 176

**REFERENZNUMMER:** -



### CONTACT



**ARSKAR AUTOMOTIVE CO. LTD.**

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak  
No: 16 Selçuklu/Konya/Türkiye

**+90.332 345 09 24**

arskar@arskar.com.tr