



## PRODUCT DETAILS

### CALIPER COMPLETE REPAIR KIT - L - (WITHOUT LEVER)



**ARSKAR NEIN** 160 840 632  
**MARKE** MERITOR  
**PAKET EINHEIT** 1 stck

## PRODUKTE ENTHALTEN



#### CALIPER PIN REPAIR KIT / 1 EINHEIT

**ARSKAR NEIN:** 160 840 195

**REFERENZNUMMER:** MCK1243, MCK1140, 85107912, 81508026025, 35403112205, 500186...



#### CALIPER ACTUATOR SEAL / 1 EINHEIT

**ARSKAR NEIN:** 160 840 227

**REFERENZNUMMER:** -



#### CALIPER ADJUSTING MECHANISM SET / 1 EINHEIT

**ARSKAR NEIN:** 160 840 086

**REFERENZNUMMER:** -



#### CALIPER MANUAL ADJUSTING GEAR - L / 1 EINHEIT

**ARSKAR NEIN:** 160 840 207

**REFERENZNUMMER:** -



#### CALIPER RUBBER CAP REPAIR KIT / 1 EINHEIT

**ARSKAR NEIN:** 160 840 634

**REFERENZNUMMER:** -



#### CALIPER BEARING SET / 1 EINHEIT

**ARSKAR NEIN:** 160 840 159

**REFERENZNUMMER:** SJ4112, 3092329, 1522169



## CONTACT



#### ARSKAR AUTOMOTIVE CO. LTD.

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak  
No: 16 Selçuklu/Konya/Türkiye

**+90.332 345 09 24**

arskar@arskar.com.tr