



**PRODUCT DETAILS**

**CALIPER PIN REPAIR KIT**



|                       |                      |
|-----------------------|----------------------|
| <b>ARSKAR NEIN</b>    | 160 840 107          |
| <b>MARKE</b>          | MERITOR              |
| <b>REFERENZNUMMER</b> | MCK1103, 81508026022 |
| <b>PAKET EINHEIT</b>  | 1 stck               |

**PRODUKTE ENTHALTEN**



**CALIPER PIN - (WITH BOLT) - Ø 28.5 / 110 MM / 1 EINHEIT**  
**ARSKAR NEIN:** 160 840 075  
**REFERENZNUMMER:** -



**CALIPER PIN - Ø 35 / 135 MM / 1 EINHEIT**  
**ARSKAR NEIN:** 160 840 068  
**REFERENZNUMMER:** -



**CALIPER PIN BOLT - M20 X 1.5 / 150 MM / 1 EINHEIT**  
**ARSKAR NEIN:** 160 840 070  
**REFERENZNUMMER:** -



**CALIPER PIN RUBBER BUSH - Ø 28.5 X 40 / 27 MM / 2 EINHEIT**  
**ARSKAR NEIN:** 160 840 076  
**REFERENZNUMMER:** -



**CALIPER PIN BUSH - Ø 35 X 39 / 30 MM / 1 EINHEIT**  
**ARSKAR NEIN:** 160 840 063  
**REFERENZNUMMER:** -



**CALIPER PIN BOOT RING - (WITH STEP) - Ø 36-37 X 39 / 15... / 1 EINHEIT**  
**ARSKAR NEIN:** 160 840 065  
**REFERENZNUMMER:** -



**CONTACT**



**ARSKAR AUTOMOTIVE CO. LTD.**

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak  
No: 16 Selçuklu/Konya/Türkiye

**+90.332 345 09 24**

arskar@arskar.com.tr

arskar.com.tr