



PRODUCT DETAILS

CALIPER COMPLETE REPAIR KIT



ARSKAR NEIN 160 840 402
MARKE MERITOR
PAKET EINHEIT 1 stck

PRODUKTE ENTHALTEN



CALIPER PIN REPAIR KIT / 1 EINHEIT

ARSKAR NEIN: 160 840 175

REFERENZNUMMER: MCK1254, AMMCK1254, ZG070160007, STRMCK1254, 871054



CALIPER ACTUATOR SEAL / 1 EINHEIT

ARSKAR NEIN: 160 840 269

REFERENZNUMMER: -



CALIPER ADJUSTING MECHANISM SET / 1 EINHEIT

ARSKAR NEIN: 160 840 265

REFERENZNUMMER: -



CALIPER MANUAL ADJUSTING GEAR / 1 EINHEIT

ARSKAR NEIN: 160 840 401

REFERENZNUMMER: -



CALIPER RUBBER CAP REPAIR KIT / 1 EINHEIT

ARSKAR NEIN: 160 840 634

REFERENZNUMMER: -



CALIPER NEEDLE BEARING SET / 1 EINHEIT

ARSKAR NEIN: 160 840 155

REFERENZNUMMER: -



CONTACT



ARSKAR AUTOMOTIVE CO. LTD.

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak
No: 16 Selçuklu/Konya/Türkiye

+90.332 345 09 24

arskar@arskar.com.tr