



PRODUCT DETAILS

CALIPER PIN REPAIR KIT



ARSKAR NEIN

160 840 153

MARKE

MERITOR

REFERENZNUMMER

MCK1299, 3092268, 3095628,
3096769, 85107718, AMMCK1299,
1522170, STRMCK1299, Y07100312

PAKET EINHEIT

1 stck

PRODUKTE ENTHALTEN



CALIPER PIN - Ø 35 / 102 MM / 1 EINHEIT

ARSKAR NEIN: 160 840 077

REFERENZNUMMER: -



CALIPER PIN BOLT - M20 X 2 / 125 MM / 2 EINHEIT

ARSKAR NEIN: 160 840 078

REFERENZNUMMER: -



CALIPER PIN BOLT - M20 X 2 / 80 MM / 1 EINHEIT

ARSKAR NEIN: 160 840 081

REFERENZNUMMER: -



CALIPER PIN CAP - Ø 40 / 18.5 MM / 2 EINHEIT

ARSKAR NEIN: 160 840 097

REFERENZNUMMER: -



CALIPER PIN BOOT / 2 EINHEIT

ARSKAR NEIN: 160 840 083

REFERENZNUMMER: -



CONTACT



ARSKAR AUTOMOTIVE CO. LTD.

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak
No: 16 Selçuklu/Konya/Türkiye

+90.332 345 09 24

arskar@arskar.com.tr