



PRODUCT DETAILS

CALIPER PIN REPAIR KIT



ARSKAR NEIN

160 840 195

MARKE

MERITOR

REFERENZNUMMER

MCK1243, MCK1140, 85107912,
81508026025, 35403112205,
5001860791, 42552052, 42555201,
503128758, 0501215220, 1522058

PAKET EINHEIT

1 stck

PRODUKTE ENTHALTEN



CALIPER PIN - Ø 35 / 144 MM / 1 EINHEIT

ARSKAR NEIN: 160 840 060

REFERENZNUMMER: -



CALIPER PIN - Ø 31 / 84 MM / 1 EINHEIT

ARSKAR NEIN: 160 840 061

REFERENZNUMMER: -



CALIPER PIN BOLT - M18 X 1.5 / 150 MM / 1 EINHEIT

ARSKAR NEIN: 160 840 088

REFERENZNUMMER: -



CALIPER PIN BOLT - M18 X 1.5 / 90 MM / 1 EINHEIT

ARSKAR NEIN: 160 840 089

REFERENZNUMMER: -



CALIPER PIN OVAL BUSH - Ø 31-33 X 42 / 30 MM / 1 EINHEIT

ARSKAR NEIN: 160 840 062

REFERENZNUMMER: -



CALIPER PIN BUSH - Ø 35 X 39 / 30 MM / 2 EINHEIT

ARSKAR NEIN: 160 840 063

REFERENZNUMMER: -



CONTACT



ARSKAR AUTOMOTIVE CO. LTD.

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak
No: 16 Selçuklu/Konya/Türkiye

+90.332 345 09 24

arskar@arskar.com.tr

arskar.com.tr