



PRODUCT DETAILS

CALIPER PIN REPAIR KIT



ARSKAR NEIN

160 840 397

MARKE

MERITOR

REFERENZNUMMER

MCK1116, 85102094, AMMCK1116,
1489197, STRMCK1116, 5021202776

PAKET EINHEIT

1 stck

PRODUKTE ENTHALTEN



CALIPER PIN - Ø 35 / 102 MM / 1 EINHEIT

ARSKAR NEIN: 160 840 077

REFERENZNUMMER: -



CALIPER PIN - Ø 35 / 60 MM / 1 EINHEIT

ARSKAR NEIN: 160 840 080

REFERENZNUMMER: -



CALIPER PIN BOLT - M20 X 2 / 125 MM / 1 EINHEIT

ARSKAR NEIN: 160 840 078

REFERENZNUMMER: -



CALIPER PIN BOLT - M20 X 2 / 80 MM / 1 EINHEIT

ARSKAR NEIN: 160 840 081

REFERENZNUMMER: -



CALIPER PIN FIBER BUSH - Ø 35 X 39 / 77 MM / 1 EINHEIT

ARSKAR NEIN: 160 840 253

REFERENZNUMMER: -



CALIPER PIN OVAL BUSH - Ø 35-36 X 39 / 30 MM / 1 EINHEIT

ARSKAR NEIN: 160 840 176

REFERENZNUMMER: -



CONTACT



ARSKAR AUTOMOTIVE CO. LTD.

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak
No: 16 Selçuklu/Konya/Türkiye

+90.332 345 09 24

arskar@arskar.com.tr

arskar.com.tr