



PRODUCT DETAILS

CALIPER PIN REPAIR KIT



ARSKAR NEIN

160 840 405

MARKE

MERITOR

REFERENZNUMMER

MCK1135, SJ4107, 3092256,
3096768, 85103891, 1522166

PAKET EINHEIT

1 stck

PRODUKTE ENTHALTEN



CALIPER PIN - Ø 35 / 102 MM / 2 EINHEIT

ARSKAR NEIN: 160 840 077

REFERENZNUMMER: -



CALIPER PIN BOLT - M20 X 2 / 125 MM / 2 EINHEIT

ARSKAR NEIN: 160 840 078

REFERENZNUMMER: -



CALIPER PIN FIBER BUSH - Ø 35 X 39 / 38 MM / 2 EINHEIT

ARSKAR NEIN: 160 840 147

REFERENZNUMMER: -



CALIPER PIN OVAL BUSH - Ø 35-36 X 39 / 30 MM / 2 EINHEIT

ARSKAR NEIN: 160 840 176

REFERENZNUMMER: -



CALIPER PIN BOOT RING - Ø 37 X 40 / 11 MM / 2 EINHEIT

ARSKAR NEIN: 160 840 105

REFERENZNUMMER: -



CALIPER PIN CAP - Ø 40 / 18.5 MM / 2 EINHEIT

ARSKAR NEIN: 160 840 097

REFERENZNUMMER: -



CONTACT



ARSKAR AUTOMOTIVE CO. LTD.

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak
No: 16 Selçuklu/Konya/Türkiye

+90.332 345 09 24

arskar@arskar.com.tr

arskar.com.tr