



## PRODUCT DETAILS

### CALIPER SHAFT & COVER REPAIR KIT



**ARSKAR NEIN**

160 840 326

**MARKE**

MERITOR

**REFERENZNUMMER**

MCK1168, MCK1169, MCK1294,  
1689883, 5021202850, 2995922,  
98133541AS, 2799441

**PAKET EINHEIT**

1 stck

### PRODUKTE ENTHALTEN



**CALIPER ECCENTRIC SHAFT / 1 EINHEIT**

**ARSKAR NEIN:** 160 840 187

**REFERENZNUMMER:** -



**CALIPER ECCENTRIC SHAFT BEVEL WASHER / 1 EINHEIT**

**ARSKAR NEIN:** 160 840 356

**REFERENZNUMMER:** -



**CALIPER ECCENTRIC SHAFT SEAL / 1 EINHEIT**

**ARSKAR NEIN:** 160 840 190

**REFERENZNUMMER:** -



**CALIPER ECCENTRIC SHAFT DUST COVER / 1 EINHEIT**

**ARSKAR NEIN:** 160 840 285

**REFERENZNUMMER:** -



**CALIPER ECCENTRIC SHAFT CENTRAL BEARING / 1 EINHEIT**

**ARSKAR NEIN:** 160 840 286

**REFERENZNUMMER:** -



**CALIPER COVER PLATE (WITH NEEDLE BEARING & SEAL) / 1 EINHEIT**

**ARSKAR NEIN:** 160 840 309

**REFERENZNUMMER:** -



### CONTACT



**ARSKAR AUTOMOTIVE CO. LTD.**

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak  
No: 16 Selçuklu/Konya/Türkiye

**+90.332 345 09 24**

arskar@arskar.com.tr

arskar.com.tr