



## PRODUCT DETAILS

### CALIPER PIN REPAIR KIT



|                         |                                                      |
|-------------------------|------------------------------------------------------|
| <b>ARSKAR NO</b>        | 160 840 405                                          |
| <b>BRAND</b>            | MERITOR                                              |
| <b>REFERENCE NUMBER</b> | MCK1135, SJ4107, 3092256, 3096768, 85103891, 1522166 |
| <b>PACKAGE UNIT</b>     | 1 pcs                                                |

### PRODUCTS INCLUDED



**CALIPER PIN - Ø 35 / 102 MM / 2 UNIT**

**ARSKAR NO:** 160 840 077

**REFERENCE NUMBER:** -



**CALIPER PIN BOLT - M20 X 2 / 125 MM / 2 UNIT**

**ARSKAR NO:** 160 840 078

**REFERENCE NUMBER:** -



**CALIPER PIN FIBER BUSH - Ø 35 X 39 / 38 MM / 2 UNIT**

**ARSKAR NO:** 160 840 147

**REFERENCE NUMBER:** -



**CALIPER PIN OVAL BUSH - Ø 35-36 X 39 / 30 MM / 2 UNIT**

**ARSKAR NO:** 160 840 176

**REFERENCE NUMBER:** -



**CALIPER PIN BOOT RING - Ø 37 X 40 / 11 MM / 2 UNIT**

**ARSKAR NO:** 160 840 105

**REFERENCE NUMBER:** -



**CALIPER PIN CAP - Ø 40 / 18.5 MM / 2 UNIT**

**ARSKAR NO:** 160 840 097

**REFERENCE NUMBER:** -



### CONTACT



**ARSKAR AUTOMOTIVE CO. LTD.**

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak  
No: 16 Selçuklu/Konya/Türkiye

**+90.332 345 09 24**

arskar@arskar.com.tr