



## PRODUCT DETAILS

### CALIPER PIN REPAIR KIT



**ARSKAR NUMMER**

160 840 205

**MERK**

MERITOR

**REFERENTIENUMMER**

MCK1298, 85109890,  
5001866989, 9500931

**PAKKET EENHEID**

1 pcs

### PRODUCTEN INBEGREPEN



**CALIPER PIN - Ø 35 / 117 MM / 1 EENHEID**

**ARSKAR NUMMER:** 160 840 235

**REFERENTIENUMMER:** -



**CALIPER PIN - Ø 31 / 78 MM / 1 EENHEID**

**ARSKAR NUMMER:** 160 840 236

**REFERENTIENUMMER:** -



**CALIPER PIN BOLT - M18 X 1.5 / 120 MM / 1 EENHEID**

**ARSKAR NUMMER:** 160 840 224

**REFERENTIENUMMER:** -



**CALIPER PIN BOLT - M18 X 1.5 / 80 MM / 1 EENHEID**

**ARSKAR NUMMER:** 160 840 225

**REFERENTIENUMMER:** -



**CALIPER PIN OVAL BUSH - Ø 31-33 X 42 / 30 MM / 1 EENHEID**

**ARSKAR NUMMER:** 160 840 062

**REFERENTIENUMMER:** -



**CALIPER PIN BUSH - Ø 35 X 39 / 30 MM / 2 EENHEID**

**ARSKAR NUMMER:** 160 840 063

**REFERENTIENUMMER:** -



### CONTACT



**ARSKAR AUTOMOTIVE CO. LTD.**

Aşağıpınarbaşı 5. Osb Mahallesi 516. Sokak  
No: 16 Selçuklu/Konya/Türkiye

**+90.332 345 09 24**

arskar@arskar.com.tr